

# Technical Manual Index

## CJ610 TURBOJET and CF700 TURBOFAN

## Component Maintenance Manual January 1, 2025

The manuals are listed in ATA number order. The Rev. Cycle column indicates the following planned revision frequency for each publication listed:

90 ----- 90 day revision cycle (Quarterly updates)  
 180 ----- 180 day revision cycle (Semi-annual updates)  
 365 ----- 365 day revision cycle (Annual updates)  
 AR ----- As Required revision cycle

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
73-11-0	SEI-154	ALL	Fuel Pump	37E501242P109 37E501242P110 37E501242P113	9234-A7 9234-A8 9234-A9	Chandler Evans (11599)	1/31/67	21	5/31/98	AR
73-12-0	SEI-154	CJ610-1/ -5/-9	Fuel Filter	37C311075P103	AC4806-45	Aircraft Porous Media (01414)	1/31/67	20	12/31/95	AR
73-13-0	SEI-154	CJ610-1/ -5/-9	Fuel Pressurizing Valve	37C301819G001	-	GE Aircraft Engines (99207)	1/31/67	20	12/31/95	AR
73-14-0	SEI-154	CJ610-1/ -5/-9	Fuel Drain Valve	37C301777G004	-	GE Aircraft Engines (99207)	1/31/67	23	8/15/00	AR
73-15-0	SEI-154	CJ610-4/ -6/-8/-8A	Fuel Pressurizing and Drain Valve	3006T88G01	-	GE Aircraft Engines (99207)	1/31/67	21	5/31/98	AR
73-16-1	SEI-154	ALL	Fuel Nozzle Assembly	37D401657P109 37D401657P110 37D401657P115	5232601 5232890 47728	GMC, Diesel Equipment Div. (71934)	1/31/67	20	12/31/95	AR
73-20-1	SEI-154	ALL	Fuel Control	5001T39 series 5002T94 series	-	GE Aircraft Engines (99207)	1/31/67	22	8/15/99	AR

# Technical Manual Index

## CJ610 TURBOJET and CF700 TURBOFAN

## Component Maintenance Manual January 1, 2025

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
73-21-0	SEI-154	CJ610-1/-4/ -5/-6/-9 CF700-2C/ -2D/-2D-2	Overspeed Governor Assembly	5006T22P02	8005-004	Woodward Governor (66503)	1/31/67	23	8/15/00	AR
73-21-1	SEI-154	ALL	Overspeed Governor Assembly	5006T14P02 5006T14P04 5012T72P01 5012T73P01	8005-008 8005-016 8005-005 8005-006	Woodward Governor (66503)	1/31/67	23	8/15/00	AR
75-10-0	SEI-154	ALL	Anti-icing Valve	37D401642P103 37D401642P104	123945-2 320765	Whittaker Corp. (79318)	1/31/67	21	5/31/98	AR
75-30-0	SEI-154	CJ610-1/ -4/-6 CF700-2C	Actuator and Arm Assembly	37E501459P101 37E501459P103	7251P101 7251P103	Arkwin Industries (98391)	1/31/67	20	12/31/95	AR
75-30-1	SEI-154	ALL	Actuator and Arm Assembly	5002T48P02	7257-3P02	Arkwin Industries (98391)	1/31/67	22	8/15/99	AR
75-31-1	SEI-154	ALL	Bleed Valve	37E501502P110 37E501502P113	378G3 378-G10	Lytron Inc. (11245)	1/31/67	20	12/31/95	AR
75-32-0	SEI-154	CJ610-4	Feedback Control Assembly	5000T47P01 5000T47P03	17221	Teleflex Inc. (78710)	1/31/67	15	5/1/77	AR

# Technical Manual Index

## CJ610 TURBOJET and CF700 TURBOFAN

## Component Maintenance Manual January 1, 2025

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
75-32-1	SEI-154	CJ610-1/-5/-9 CF700-2C/-2D/-2D-2	Feedback Control Assembly	6003T46P01	22614	Teleflex Inc. (78710)	1/31/67	15	5/1/77	AR
75-32-2	SEI-154	CJ610-4/-6/-8/-8A	Feedback Control Assembly	5003T58P01	22601	Teleflex Inc. (78710)	1/31/67	15	5/1/77	AR
75-33-0	SEI-154	ALL	Synchronizing Cable Assembly and Adjusting Link	4006T61P01	22722	Teleflex Inc. (78710)	1/31/67	14	4/1/76	AR
77-11-0	SEI-154	CJ610-1/-4/-5/-6/-8/-8A/-9	Exhaust Pressure Probe	37D401739P101 37D401739P108	—	GE Aircraft Engines (99207)	1/31/67	19	11/1/84	AR
77-11-1	SEI-154	CF700-2C/-2D/-2D-2	Exhaust Pressure Probe	5014T22G01 5014T22G02	—	GE Aircraft Engines (99207)	1/31/67	19	11/1/84	AR
77-20-0	SEI-154	CJ610-1/-4	Thermocouple Harness Assembly	37E501519P102	AA-1375-2	Atlas Aero Corp. (09526)	1/31/67	17	5/1/79	AR
77-20-1	SEI-154	CF700-2C/-2D/-2D-2	Thermocouple Harness Assembly	6012T16P03	8TE16AAM	Ametek Aerospace Products (97424)	1/31/67	17	5/1/79	AR

# Technical Manual Index

## CJ610 TURBOJET and CF700 TURBOFAN

## Component Maintenance Manual January 1, 2025

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
77-20-2	SEI-154	CF700-2C/ -2D/-2D-2	Thermocouple Harness Assembly	6014T95P01	8TE16AAV	Ametek Aerospace Products (97424)	1/31/67	20	12/31/95	AR
77-30-0	SEI-154	CF700-2C/ -2D/-2D-2	Speed Sensor	3002T86P02 4011T92P01 4049T17P01	721748 721748B 724715	Electro Products Laboratories Inc. (81692)	1/31/67	16	4/1/78	AR
77-40-0	SEI-154	CJ610-9 CF700-2C/ -2D/-2D-2	Engine Temperature Protector	7022M30G01 7022M31G02 7022M31G03	—	GE Aircraft Engines (99207)	1/31/67	19	11/1/84	AR
77-40-1	SEI-154	CJ610-9	Engine Temperature Protector	4025T42P01	8TK25AAA1	Ametek Aerospace Products (97424)	1/31/67	20	12/31/95	AR
79-10-0	SEI-154	CF700-2C	Oil Tank Assembly	6002T03P04	UA526213-11	United Aircraft Products (78943)	1/31/67	11	4/1/71	AR
79-10-1	SEI-154	CJ610-1/ -5/-9 CF700-2C/ -2D/-2D-2	Oil Tank Assembly	6003T09P04	52000-153	Alloytek Inc. (55806)	1/31/67	20	12/31/95	AR
79-10-2	SEI-154	CJ610-4/ -6/-8/-8A	Oil Tank Assembly	6003T89P01 6003T89P02	52000-112 52000-113	Alloytek Inc. (55806)	1/31/67	21	5/31/98	AR

# Technical Manual Index

## CJ610 TURBOJET and CF700 TURBOFAN

## Component Maintenance Manual January 1, 2025

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
79-20-2	SEI-154	CJ610-1/-4/ -5/-6/-8/ -8A/-9	Lube and Scavenge Pump	37R601003P104 37R601003P112	RR16500A3 RR16500A18	Lear Siegler Inc. (51663)	1/31/67	23	8/15/00	AR
79-20-3	SEI-154	CF700-2C/ -2D/-2D-2	Lube and Scavenge Pump	37R601209P109	RR17780G	Lear Siegler Inc. (51663)	1/31/67	20	12/31/95	AR
79-21-0	SEI-154	CF700-2C/ -2D/-2D-2	Fan Scavenge Pump	4003T54P01	GD302-1	W. H. Nichols (86329)	1/31/67	21	5/31/98	AR
79-22-0	SEI-154	CJ610-1/-4 CF700-2C	Oil Filter Assembly	37C301062P103	R9W353	North American Rockwell (00736)	1/31/67	14	4/1/76	AR
79-22-1	SEI-154	CJ610-1/-4/ -5/-6 CF700-2C/ -2D/-2D-2	Oil Filter Assembly	3005T78G01	R9W818	North American Rockwell (00736)	1/31/67	14	4/1/76	AR
79-22-2	SEI-154	CJ610-1/-4/ -5/-6 CF700-2C/ -2D/-2D-2	Oil Filter Assembly	3005T78G01	54207-1	Cuno Engineering (15472)	1/31/67	14	4/1/76	AR
79-22-3	SEI-154	ALL	Oil Filter Assembly	3015T00G01	—	GE Aircraft Engines (99207)	1/31/67	9	4/1/70	AR
79-22-4	SEI-154	ALL	Oil Filter Assembly	3015T00G03	R9W1210	GE Aircraft Engines (99207)	1/31/67	13	5/1/73	AR

# Technical Manual Index

## CJ610 TURBOJET and CF700 TURBOFAN

## Component Maintenance Manual January 1, 2025

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
79-22-5	SEI-154	ALL	Oil Filter Assembly	3015T00G04	54359-01	GE Aircraft Engines (99207)	1/31/67	13	5/1/73	AR
79-23-0	SEI-154	ALL	Oil Cooler Assembly	37D401061P108 37D401061P108	154410-6-1 154410-6-2	Air Research Mfg. (70210)	1/31/67	20	12/31/95	AR
79-40-0	SEI-154	CJ610-1/-4 CF700-2C	Oil Tank Relief Valve	37C301075P102	LH10420	Lourdes Industries (01178)	1/31/67	23	8/15/00	AR
79-40-1	SEI-154	ALL	Oil Tank Relief Valve	37C301075P102 37C301075P10437 C301075P105	K-1221-8-2 K-1221-8-6 K-1221-8-10	Kohler Co. (34199)	1/31/67	11	4/1/71	AR
79-40-2	SEI-154	CJ610-1/-4 CF700-2C	Oil Tank Relief Valve	37C301075P102	1112-599355	Parker Aircraft Co. (92003)	1/31/67	0	1/31/67	AR
79-43-0	SEI-154	CJ610-1	Air Leakage Check Valve	37D401330G003	—	GE Aircraft Engines (99207)	1/31/67	20	12/31/95	AR
79-43-1	SEI-154	ALL	Air Leakage Check Valve	4001T94G05 4001T94G06 4001T94G08 4001T94G09 4003T41G01	—	GE Aircraft Engines (99207)	1/31/67	20	12/31/95	AR
80-20-0	SEI-154	CJ610-1/-5/ -9 CF700-2C/ -2D/-2D-2	Ignition Exciter	37D401588P103	10-324330-3	Unison Industries (59501)	1/31/67	20	12/31/95	AR

# Technical Manual Index

## CJ610 TURBOJET and CF700 TURBOFAN

Component Maintenance Manual  
January 1, 2025

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
80-20-1	SEI-154	CJ610-1/-4/ -5/-6 CF700-2C	Ignition Exciter	4006T58P01 4006T58P03	42473 43249	Unison Industries (83311)	1/31/67	22	8/15/99	AR
80-20-2	SEI-154	ALL	Ignition Exciter	4026T03P01	43467K	Unison Industries (83311)	1/31/67	23	8/15/00	AR
80-21-0	SEI-154	ALL	Ignition Lead Assembly	37C311098P101 37C311098P102	59616 (Right hand) 59617 (Left hand)	Co-Operative Industries (81482)	1/31/67	22	8/15/99	AR
80-22-0	SEI-154	CJ610-1/-4/ -5/-6/-9 CF700-2C/ -2D/-2D-2	Igniter Plug	37C311124P101	FHE146-7	Champion (11583)	1/31/67	22	8/15/99	AR
80-22-0	SEI-154	ALL	Igniter Plug	37C311124P102 4013T35P01	10-360345-1 10-360947-1	Bendix Corp. (77820)	1/31/67	14	4/1/76	AR

Questions or comments concerning the content of this index should be directed to [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com).