

Technical Manual Index

CT64-820-4 Turboprop

Component Maintenance Manual
January 1, 2025

The manuals are listed in appendix number order.

The Rev. Cycle column indicates the following planned revision frequency for each publication listed:

AR - - - - - As Required revision cycle

| <u>Appendix Number</u> | <u>Publ. Number</u> | <u>Engine Model</u> | <u>Nomenclature</u> | <u>Part Number</u> | <u>VIN</u> | <u>Manufacturer Name (Vendor Code)</u> | <u>Basic Issue Date</u> | <u>Rev. No.</u> | <u>Rev. Date</u> | <u>Rev. Cycle</u> |
|------------------------|---------------------|---------------------|-----------------------------------|--|--|--|-------------------------|-----------------|------------------|-------------------|
| A1 & A2 | SEI-409 | CT64-820-4 | Fuel Control | 6028T87P01 6028T87P02 6028T87P04 | 757520-1 757520-2 757520-4 | Hamilton Sundstrand (73030) | 5/30/76 | 10 | 10/15/16 | AR |
| A3 | SEI-409 | CT64-820-4 | Lube & Scavenge Pump (Power Unit) | 5008T68P10 | GD-321-13 | Nichols Zenith Div, Parker Hannifin Corp. (86329) | 5/30/76 | 10 | 10/15/16 | AR |
| A4 | SEI-409 | CT64-820-4 | Lube & Scavenge Pump (SDG) | 5006T88P01 5006T88P03 5006T88P05 5006T88P06 5006T88P07 5006T88P08 | GM-555 GM-555-2 GM-555-4 GM-555-6 GM-555-7 GM-555-8 | Parker Hannifin Corp. Parker Aerospace Fluid Systems Division (86329) | 5/30/76 | 10 | 10/15/16 | AR |
| A5 & A6 | SEI-409 | CT64-820-4 | Ignition Exciter | 4022T65P01 | 43661 | Unison Industries (59501) | 5/30/76 | 10 | 10/15/16 | AR |
| A7 & A8 | SEI-409 | CT64-820-4 | Fuel Pump and Filter | 5012T70P03 | 024836-117 | Hamilton Sundstrand (73030) | 5/30/76 | 10 | 10/15/16 | AR |

Technical Manual Index

CT64-820-4 Turboprop

Component Maintenance Manual
January 1, 2025

| Appendix Number | Publ. Number | Engine Model | Nomenclature | Part Number | VIN | Manufacturer Name (Vendor Code) | Basic Issue Date | Rev. No. | Rev. Date | Rev. Cycle |
|-----------------|--------------|--------------|----------------------------|--|------------|---------------------------------|------------------|----------|-----------|------------|
| A9 | SEI-409 | CT64-820-4 | Variable Geometry Actuator | 5006T68G04 5006T68G07 5006T68G09 | | GE Aircraft Engines (99207) | 5/30/76 | 10 | 10/15/16 | AR |
| A10 | SEI-409 | CT64-820-4 | Flow Divider | 5006T26G04 | | GE Aircraft Engines (99207) | 5/30/76 | 10 | 10/15/16 | AR |
| A11 | SEI-409 | CT64-820-4 | Anti-Icing Valve | 4008T21P03 4008T21P05 | DC 10705-1 | GE Aircraft Engines (99207) | 5/30/76 | 10 | 10/15/16 | AR |
| A12 | SEI-409 | CT64-820-4 | Fuel Nozzle Assembly | 4015T51P03 | 25007 | Delavan Inc. (71895) | 5/30/76 | 10 | 10/15/16 | AR |

Questions or comments concerning the content of this index should be directed to aviation.fleetsupport@ge.com.