

QUALITY REMARK: AEPD  
QUALITY REQUIREMENT E50

SOURCE SUBSTANTIATION IS NOT REQUIRED. HOWEVER, SOURCES OF SPECIAL PROCESSES SHALL BE CERTIFIED PER THE REQUIREMENTS OF S-1000 FOR GEAE DRAWINGS.