

QUALITY REMARK: AEPD
REQUIREMENT NUMBER 535

IN ADDITION TO THE MARKING SPECIFIED BY THE DRAWING OR SPECIFICATION, MARK EACH PART WITH THE LETTER K BELOW THE DESIGNATED MARKING AREA. IF SPACE DOES NOT PERMIT, THEN MARK ADJACENT TO, BUT SEPARATE FROM, THE PART NUMBER/SERIAL NUMBER MARKING. WHERE IT IS IMPRACTICAL TO APPLY THE K WITH THE SAME MARKING METHOD, CONTACT THE PURCHASER FOR DIRECTION CONCERNING WHAT METHOD TO USE. WHERE THE PART IS TOO SMALL OR FRAGILE, MARK THE CONTAINER WITH THE LETTER K.