

QUALITY REMARK: S.E.O.
S.E.O. QUALITY REQUIREMENT NUMBER 693

SELLER WILL DOCUMENT FIRST ARTICLE INSPECTION ON FIRST PIECE CONSISTING OF 100 PERCENT COMPLIANCE TO GE DRAWING REQUIREMENTS, INCLUDING DIMENSIONAL, FUNCTIONAL TEST, SPECIAL PROCESSES AND LABORATORY REQUIREMENTS ON FORM QC-251. VARIABLE DATA SHALL BE DOCUMENTED WHEN VARIABLE TYPE METHODS OF INSPECTION ARE APPLIED. IF INSPECTION TECHNIQUE DOES NOT PROVIDE VARIABLE DATA, THE REPORT WILL IDENTIFY THE METHOD OF INSPECTION.

A CHANGE VIA A GROUP/PART NUMBER CHANGE WILL REQUIRE FIRST ARTICLE INSPECTION OF ONLY THE CHANGES OR ADDED CHARACTERISTICS. A PART WHICH IS PART OF AN ASSEMBLY DOES NOT NEED A NEW FIRST ARTICLE INSPECTION IF ONE HAD BEEN PREVIOUSLY PERFORMED. THE QC-251 WILL REFERENCE THE PREVIOUS FIRST ARTICLE PART NUMBER. DOCUMENTATION TO ACCOMPANY FIRST SHIPMENT OF MATERIAL WILL BE ATTACHED TO PACKING SLIP.