

QUALITY REMARK: AEPD
QUALITY REQUIREMENT D75.

GEAE FIELD PRODUCT/PROCESS SURVEILLANCE PLAN APPLIES TO THIS ORDER.
ALL MATERIALS SHIPPED VIA THIS ORDER MUST BE ACCOMPANIED BY A PACKING
SLIP WHICH IS STAMPED IN ACCORDANCE WITH THE REQUIREMENTS OF THE
FIELD PRODUCT/PROCESS SURVEILLANCE PLAN. THE STAMP ON THE PACKING
SLIP IS TO BE SIGNED BY THE SUPPLIER'S DS QUALITY REPRESENTATIVE WHO
IS QUALIFIED IN ACCORDANCE WITH THAT PLAN AND WHOSE ASSIGNED STAMP IS
SO USED. A GEAE QUALITY REPRESENTATIVE MAY ALSO APPLY AND SIGN USING
THEIR ASSIGNED STAMP.