

QUALITY REMARK: SUPPORT EQUIP  
STANDARD REMARK F19

THE USE OF SPECIFICATION S-500 AND ITS INCLUDED FORMS, AS SPECIFIED IN S-1000B, PART III, PARAGRAPH I, IS NOT REQUIRED ON THIS ORDER. THE SUPPLIER IS RESPONSIBLE TO ACCOUNT FOR, VERIFY, AND RECORD ALL CHARACTERISTICS OF THE APPLICABLE GE DRAWINGS AND SPECIFICATIONS. ALL CRITICAL, MAJOR, FUNCTIONAL, CYCLIC, AND THREE AND FOUR PLACE DIMENSIONAL CHARACTERISTICS, MUST BE RECORDED ON FORM QC251. THE BALANCE OF THE CHARACTERISTICS MAY BE RECORDED WHERE VARIABLE INSPECTION METHODS ARE UTILIZED. COMPLIANCE WITH SPECIFICATIONS MAY BE RECORDED ON THE QC251 FORM AS A SINGLE ENTRY. RECORDS DOCUMENTING ALL CHARACTERISTICS MUST BE KEPT ON FILE BY THE SUPPLIER, AND MUST BE AVAILABLE TO GE UPON REQUEST.